BREWSTER

PUTNAM COUNTY DEPARTMENT OF HEALTH

Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION ADDRESS OWNER J. Lewis General Contracto 60 Fairfield Drive, Patterson, NY s, (No. & Street) LOCATION (Town) (Lot Number) South Drive Brewster, New York OF WELL BUSINESS X DOMESTIC PROPOSED ESTABLISHMENT FARM TEST WELL USE OF 6010 PUBLIC WELL AIR OTHER SUPPLY INDUSTRIAL CONDITIONING (Specify) DRILLING COMPRESSED CARLE ROTARY OTHER (Specify) EQUIPMENT AIR PERCUSSION PERCUSSION LENGTH (feet) DIAMETER (Inches) WEIGHT PER FOOT DRIVE SHOE CASING WAS CASING GROUTED? 115 DETAILS б 17 THREADED 20 YES X YES WELDED NO NO HOURS YIELD C. P.M YIELD (G.P.M.) BAILED COMPRESSED AIR PUMPED TEST 4 10 10 MEASURE FROM LAND SURFACE - STATIC (Specify feet) DURING YIELD TEST (feet) WATER Depth of Completed Well 65 LEVEL 345 345 in feet below Land surface: LENGTH OPEN TO AQUIFER (feet) SCREEN SLOT SIZE DETAILS DIAMETER (Inches) GRAVEL SIZE (Inches) FROM (IMMI) TO //eeti IF GRAVEL Diameter of well including PACKED: gravel pack (Inches): DEFTH FROM LAND SURFACE Sketch exact location of wall with distances, to at least FORMATION DESCRIPTION PEET to FEET two permanent landmarks 0 105 Grey Hardpan @-Well 105 345 Black & Grey Granite Dwelling RECEIVED AUG 3 0 1982 PUTNAM COUNTY DEPT. OF HEALTH If yield was tested at different depths during drilling, list below FEET GALLONS PER MINUTE Proposed D 3 Driveud South Drive DATE WELL COMPLETED DATE OF REPORT WELL DRILLER (Signature) 7/13/82